



What's wrong with this picture?

Workers on a roof greater than 25 feet from eave to ground with no fall protection