



**What's wrong with this picture?**

**Walking on the top plate higher than six feet with no fall protection and working on a carpenter's bracket scaffold higher than 10 feet with no fall protection**